	Air conditioning	 Joystick control
Romco Equipment Co	Directional lights	 External rearview mirrors
Carrollton, TX	Quick Coupler	 Ride control system
817-626-2288	Air suspension seat	
	• SMU/Hours: 5936	Start Run: Yes
	Overall: Fair	 Insp Date: 11/20/2017



(Continued)

General Appearance

Radiator Grille:	Good	Fuel Tank:	Good	
Radiator Shroud:	Good	Cab Doors:	Good	
Engine Enclosure:	Good	Bumper:	Good	
Hood:	Good	Differential supports:	Good	
Stack:	Good	Counterweight:	Good	
Right front fender:	Good	Cab:	Good	
Left front fender:	Good	Steps:	Fair	
Right rear fender:	Good	Grab Irons/Handrails:	Good	
Left rear fender:	Good	Paint:	Fair	
Main Frame:	Good	Oil Sample Taken:	No	
Precleaner bowl:	Good			

Interior Section

Glass:	Fair	Neutral Start Switch:	Good	
Mirrors:	Good	Fire Suppression System:	Not Available	
Seat Belt:	Good	Horn:	Good	
Back Up Alarm:	Good	Roll Over Protection:	ROPS	
Fan Guards:	Good			
NOTES:				
OPERATOR AREA:				
Dash Console:	Good	Seat Cushion:	Good	
Meter:	Good	Arm Rests:	Good	
Gauges:	Good	Floor Boards/Mats:	Good	
Control Pattern Decals:	Good	EMS Panel:	Good	
Switches:	Good	Warnings:	Good	
Windshield W ipers:	Good	Door Latches:	Good	
Heater:	Good	Current Parts Manual:	No	
A/C:	Good	Current Safety Manual:	No	
Interior Lights:	Poor	Current O&M Manual:	Yes	

Power Systems

Engine Make Model:	Volvo D6H	Oil Pressure:	Normal	
Engine S/N:	11702396	Smoke:	No	
+Engine Hours:	5936	Smoke Color:	Not Applicable	
Mechanical: 6060		TurboCharger:	Good	
Oil Leaks:	No	Fuel Injection System:	Good	
Blow-by:	No	Governor:	Good	
Knocking:	No	Engine Supports:	Good	
Compression in Radiator:	No	Air Cleaners:	Good	
Water in Oil:	No	Last Scheduled Oil Sample:	N/A	
Fluid Level OK?:	Yes	Last Preventive Maintenance:	N/A	
Anit-Freeze Color:	Red			
COOLING SYSTEM:				
Radiator:	Good	Fan:	Good	
Coolers:	Good	Fan Drive:	Good	
Hoses:	Good	Belts:	Good	
Water Pump:	Good	Pulleys:	Good	
NOTES:				
ELECTRICAL SYSTEM:				
Batteries:	Good	Wiring:	Good	
Battery Cables:	Good	Pre-Heater:	Good	
	Good	Lighting:	Poor	
Starter:				



(Continued)

Power Systems - Continued

Serial #:	N/A	Controls:	Good
Туре:	APS	Seals:	Good
Speeds:	Excellent	Torque Converter:	Good
Transmission Forward:	Good	Temp/Pressure Gauges:	Good
Transmission Reverse:	Good	Is the Transmission Noisy?:	No
Case:	Good		
NOTES:		,	
STEERING:			
Front axle:	Not Available	Articulation P & B:	Good
Steering Linkage:	Good	Steering cylinder:	Good
Steering V alve:	Good	Tie rods/ rod ends:	Not Available
Steering Pump:	Good		
NOTES:			
BRAKE:			
Mechanism:	Wet	Lines:	Good
Brake Type:	Pedal	Compressor:	Not Available
Performance:	Good	Brake linkage:	Good
Brake drums:	Not Available	Master cylinder:	Good
Rotors:	Good	Parking brake:	Good
Control V alve:	Good		
NOTES:			
FINAL DRIVE:			
Front Planataries:	Good	Rear Wheel lugs & rims:	Good
Front Differential:	Good	Front Axle bolts:	Good
Rear Planataries:	Good	Rear Axle bolts:	Good
	Good	Front axle housings:	Good
Rear Differential:	0000	Ŭ	

(Continued)

Hydraulics

Right lift cylinder:	Good	Pumps:	Good	
Left lift cylinder:	Good	Valves:	Good	
Bucket cylinder:	Good	Control linkage:	Good	
Hose lines:	Good	Bucket & hoist kickout:	Good	

(Continued)

Front Bucket

Bucket T ype:	General Purpose	Bucket adapters:	Not Available	
Width:	102 Inches	Bucket teeth:	Not Available	
Capacity:	N/A	Arms & cranks:	Good	
Bucket bottom:	Good	Loader frame:	Good	
Bucket sides:	Good	Loader P & B:	Good	
Bucket linkage:	Good	Quick coupler:	Good	
Bucket mounts:	Good			

LeaseInspector Off-Lease

2015 Volvo L90G

(Continued)

Tires

TIRES:					
Front T ire Size:	Left: 20.5R25- 59%	Right: 20.5R25- 59%	Rear Tire Size:	Left: 20.5R25- 19%	Right: 20.5R25- 35%
Front T ire Brand:	Left: Bridgestone	Right: Bridgestone	Rear Tire Brand:	Left: BridgestoneF	Right: Bridgestone
Front T ire Measurement:	Left: 25/32	Right: 25/32	Rear Tire Measurement:	Left: 8/32	Right: 15/32
NOTES:					



(Continued)

Comments

COMMENTS:

Creditor Comments: Has Rear View Camera


Public Comments:


Has Rear View Camera

(Continued)


Deficiency Review

DE	FICIENCY REVIEW:	
	ITEM	QTY PRICE
1.	3 Front Work Lights Inop	\$0.00
2.	Left Headlight Inop	\$0.00
3.	Right Headlight Inop	\$0.00
4.	Right Windshield Cracked	\$0.00
5.	Dome Light Inop	\$0.00
6.	1 Vent Louver Damaged	\$0.00
7.	Cab Steps Bent	\$0.00
8.	Right Side Steps Bent	\$0.00
9.	Left Rear Blinker Lens Cracked	\$0.00
10.	Coupler Has Lock Fault Code	\$0.00
11.	Battery Disconnect Key Missing	\$0.00
12.	Radio Slot Blank Plate Missing	\$0.00
13.	Replace Reat Tires Worn Past 50%	\$0.00
14.	Clean Machine	\$0.00
Tot	al	\$0.00







(Continued)

















(Continued)



