VOLVO - INSPECTION REPORT

Volvo, EC480EL - Track Excavators

Images























Comment:

Country: US Date: 09/04/2019 Make: Volvo

Serial number: 310387

Dealer: Alta Equipment Company

Inspector: Anthony M Model: EC480EL Engine S/N: 582902

Location: New Hudson

Year: 2016 Hours: 5683 Matris hours: 5692

Comment:

Equipped Configuration

[X] Yes EROPS

[X] Yes Air conditioning

] Yes Stick short

[X] Yes Stick medium

] Yes 2 Piece boom

1 Yes Long reach arrangement

] Yes Drill arrangement

] Yes Recycling arrangement

] Yes Demolition arrangement

] Yes Mass excavator arrangement

[] Yes Forestry arrangement

] Yes Cab risers

] Yes Cab riser hydraulic

X] Yes Standard car body

] Yes Hydraulic retractable UC

] Yes Auxiliary hydraulics

1 Yes Hose rupture valves **1 Yes** Boom float

1 Yes Attachment circuits

] Yes Leveling blade

] Yes Cushion boom cylinder

[X] Yes Proportional joystick controls

[X] Yes Joystick controls

] Yes Thumb - Manual

] Yes Thumb hydraulic

[X] Yes Counterweight removal sys.

[] Yes Long undercarriage

] Yes Quick coupler manual

1 Yes Quick coupler hydraulic

] Yes Auto Lube

[X] Yes Travel pedal

Operators Station

Comment:

Seat and armrest [X] Fair Remarks: burn hole in seat bottom. operators station does not slide forward or back but seat does.

Dash and console [X] Good

Floor Board/Mat [X] Good

Cab glass [X] Good

Mirrors [X] Good

Interior light [X] Good

Switches	[X] Good	
Wipers	[X] Good	
Gauges	[X] Good	
Hydraulic controls	[X] Good	
Powertrain controls	[X] Good	
AC cooling	[X] Good	
CAB Interior	[X] Good	
Operators station		_
condition summary		
Comment:		



Outside appearance

Steps	[X] Good		
Hand rails	[X] Good		
Counterweight /	[X] Good		
Bumper			
Grill	[X] Good		
Hood	[X] Good		
Exhaust stack	[X] Good		
Pre-cleaner bowl	[X] Good		
Front fenders	[X] Good		
Hyd tank	[X] Good		
Fuel tank	[X] Good		
Car body	[X] Good		
Fenders	[X] Good		
OEM Welds	[X] Good		
Sheet metal	[X] Good		
Paint	[X] Good		
Outside appearance condition summary			

Safety condition

Comment:

Safety decals in place [X] Yes
Operators manual [X] No
Safety handles [X] Good
Seat belt [X] Good
Horn [X] Good
Back up alarm [X] Good

Brake hold	[X] Good	
ROPS Structure	[X] Good	
Guarding	[X] Good	
CAB	[X] Good	
Safety condition summary		
Comment:		
Electrical condition		
Computer	[X] Good	
ECM'S	[X] Good	
Monitor / Display	[X] Good	
Wiring harness's	[X] Good	
Key switch	[X] Good	
Switches	[X] Good	
Lighting	[X] Good	
Engine preheater	[X] Good	
Batteries / Connections		
Battery disconnect switch	[X] Good	
Electrical condition summary]
Comment:		
Engine condition Oil level OK	[X]Yes	
Water in oil	[X]No	
Compression	[X] No	
Blow by	[X]No	
Engine knocking	[X]No	
CE PLATE	[]Yes []No	
Oil pressure	[X] Good	
Oil leaks	[X]No	
EPA DECAL	[X] Yes	
Turbo charger	[X] Good	
Exhaust manifold	[X] Good	
Muffler	[X] Good	
Fuel injection system	[X] Good	
Head gasket	[X] Good	
Head	[X] Good	

Fan guard	[X] Good
Belts & pulleys	[X] Good
Wiring harness	[X] Good
Starter	[X] Good
Alternator	[X] Good
Seals & gaskets	[X] Good
Engine mounts	[X] Good
Brackets	[X] Good
AC Compressor	[X] Good
Air filters	[X] Good
Engine condition summary	
Comment:	
Cooling system	
Coolant color	yellow
Radiator	[X] Good
Water pump	[X] Good
Oil cooler	[X] Good
Fan	[X] Good
Fan drive	[X] Good
Hoses	[X] Good
Cooling system summary	
Comment:	
Hydraulics cond	ition
Boom cylinders	[X] Good
Stick cylinders	[X] Good
Bucket cylinders	[X] Good
Blade cylinders	[] Good [] Fair [] Poor Remarks:
Thumb cylinders	[] Good [] Fair [] Poor Remarks:
Pumps	[X] Good
Valves	[X] Good
Hoses	[X] Good
Fittings	[X] Good
Tank	[X] Good
Swing bearing	[X] Good
Swing gear	[X] Good

Swing motor	[X] Good
Hydraulic swivel	[X] Good
Travel motors	[X] Good
Pump drive	[X] Good
Planetaries left	[X] Good
Planetaries right	[X] Good
Controls	[X] Good
Overall condition	[X] Good
Summary	
Comment:	counter weight bolts are just hand tight for removal for shipping.
Boom & arm cond	lition
Lower stick pins	[X] Good
Upper stick pins	[X] Good
Stick condition	[X] Good
Stick length	3.9M
Boom length	7.0M
Lower boom pins	[X] Good
Upper boom pins	[X] Good
Boom condition	[X] Good
Summary	
Comment:	
Bucket & other att	tachments
Developt to the Alice	
Bucket type / Size	Geith 4.75 cyd
Coupler type	none
Bucket serial	332064
Coupler serial	none
Bucket W / Teeth	[X]Yes
Addtl attachments	
Bolt on smooth	[X]No
Bolt on edge	[] Good [] Fair [] Poor Remarks:
Bucket mounts	[X] Good
Bucket teeth / Segments	[X] Good
Bucket sides	[X] Good
Bucket floor	[X] Good

Bucket bottom	[X] Good
Coupler	[] Good [] Fair [] Poor Remarks:
Boom / Frame	[X] Good
Boom / Bucket pins & bushings	[X] Good
Summary	
Comment:	
Undercarriage con	dition
Roller frame right	[X] Good
Roller frame left	[X] Good
Track adjusters	[X] Good
Overall condition	[X] Good
Links left	126
Links left	50%
Internal pin wear left	216
Internal pin wear left	50%
External pin wear left	71
External pin wear left	25%
Trackshoe/ Grouser left	34
Trackshoe/ Grouser left	75%
Front Idler left	25
Front Idler left	50%
Sprockets left	7
Sprockets left	10%
Front Carrier Rollers left	158
Front Carrier Rollers left	30%
Center Carrier Rollers left	
Center Carrier Rollers left	
Rear Carrier Rollers	158

left

left	35%	
Links right	126	
Links right	50%	
Internal pin wear right	216	
Internal pin wear right	50%	
External pin wear right	71	
External pin wear right	25%	
Trackshoe/ Grouser right	34	
Trackshoe/ Grouser right	75%	
Front Idler right	25	
Front Idler right	50%	
Sprockets right	7	
Sprockets right	10%	
Front Carrier Rollers right	158	
Front Carrier Rollers right	30%	
Center Carrier Rollers right		
Center Carrier Rollers right		
Rear Carrier Rollers right	158	
Rear Carrier Rollers right	30%	
Bottom rollers S or D	S	
Undercarriage brand	volvo	
Link part number	N/A	
Pins & bushings turned	ON	
Comment:	worn out	
Bottom rollers S o	r D	
Bottom rollers S	S or D left (mm) Bottom rollers S or D left (%) Bottom rollers S or D right (mm)
193	mm 30%	193 mm
Bottom rollers S		
30%		30%
Bottom rollers S		
193 Bottom rollers	mm S or D left (%) Bottom rollers S or D right (i	
30%	S or D left (%) Bottom rollers S or D right (i	30%
Bottom rollers S		
193	mm Solution	193 mm
Bottom rollers S		

mm

30%

30%

193

Bottom rollers S	or D right (mm)	Bottom rollers S or D r	ight (%)	Bottom rollers S or I	D left (mm)
193	mm	30%	193	3	mm
Bottom rollers S	S or D left (%)	Bottom rollers S or D ri	ght (mm)	Bottom rollers S or I	D right (%)
30%		193 r	nm	30%	
Bottom rollers S	or D left (mm)	Bottom rollers S or D	left (%)	Bottom rollers S or D	right (mm)
193	mm	30%	193	3	mm
Bottom rollers S	or D right (%)	Bottom rollers S or D le	eft (mm)	Bottom rollers S or	D left (%)
30%		193 r	mm	30%	
Bottom rollers S	or D right (mm)	Bottom rollers S or D r	ight (%)	Bottom rollers S or I	D left (mm)
193	mm	30%	193	3	mm
Bottom rollers S	S or D left (%)	Bottom rollers S or D rig	ght (mm)	Bottom rollers S or I	D right (%)
30%		193 r	mm	30%	
Bottom rollers S	or D left (mm)	Bottom rollers S or D	left (%)	Bottom rollers S or D	right (mm)
193	mm	30%	193	3	mm
Bottom rollers S	or D right (%)				
30%					
Comment:					
General Comments					
Legend (5 star rating)	[X]4				
Paint general	[X] Good				
Comment:					