# **VOLVO - INSPECTION REPORT**

# Volvo, Ec220e - Track Excavators

Images





Country: US Date: 08/19/2019 Aake: Volvo Serial number: 310492	Dealer: Arnold Machinery Company Inspector: Mike seifert Model: Ec220e Engine S/N: 11993537	Location: Las vegas Year: 2017 Hours: 2896 Matris hours: 2895	
Comment:	<b>.</b>		
quipped Configuration			
iquipped comigatation			
	I I Vos Cabrisors	[X] Vas Proportional joystick controls	
[X] Yes EROPS	I Yes Cab risers     I Yes Cab riser hydraulic	[X] Yes Proportional joystick controls	
[X] Yes Air conditioning	[ ] Yes Cab riser hydraulic	[X] Yes Joystick controls	
X ] Yes Air conditioning Yes Stick short	[ ] Yes Cab riser hydraulic [X] Yes Standard car body	[X] Yes Joystick controls [ ] Yes Thumb - Manual	
[X] Yes Air conditioning	Yes Cab riser hydraulic         Yes Standard car body         Yes Hydraulic retractable UC	[ X ] Yes Joystick controls [ ] Yes Thumb - Manual [ X ] Yes Thumb hydraulic	
X ] Yes Air conditioning [ ] Yes Stick short [ X ] Yes Stick medium	[ ] Yes Cab riser hydraulic [X] Yes Standard car body	[X] Yes Joystick controls [ ] Yes Thumb - Manual	
<ul> <li>[X] Yes Air conditioning</li> <li>[] Yes Stick short</li> <li>[X] Yes Stick medium</li> <li>[] Yes 2 Piece boom</li> </ul>	Yes Cab riser hydraulic         Yes Standard car body         Yes Hydraulic retractable UC         X Yes Auxiliary hydraulics	<ul> <li>[X] Yes Joystick controls</li> <li>[] Yes Thumb - Manual</li> <li>[X] Yes Thumb hydraulic</li> <li>[] Yes Counterweight removal sys.</li> </ul>	
<ul> <li>[X] Yes Air conditioning</li> <li>[] Yes Stick short</li> <li>[X] Yes Stick medium</li> <li>[] Yes 2 Piece boom</li> <li>[] Yes Long reach arrangement</li> </ul>	<ul> <li>Yes Cab riser hydraulic</li> <li>Yes Standard car body</li> <li>Yes Hydraulic retractable UC</li> <li>Yes Auxiliary hydraulics</li> <li>Yes Hose rupture valves</li> </ul>	<ul> <li>[X] Yes Joystick controls</li> <li>[] Yes Thumb - Manual</li> <li>[X] Yes Thumb hydraulic</li> <li>[] Yes Counterweight removal sys.</li> <li>[X] Yes Long undercarriage</li> </ul>	
<ul> <li>[X] Yes Air conditioning</li> <li>[] Yes Stick short</li> <li>[X] Yes Stick medium</li> <li>[] Yes 2 Piece boom</li> <li>[] Yes Long reach arrangement</li> <li>[] Yes Drill arrangement</li> </ul>	<ul> <li>Yes Cab riser hydraulic</li> <li>Yes Standard car body</li> <li>Yes Hydraulic retractable UC</li> <li>Yes Auxiliary hydraulics</li> <li>Yes Hose rupture valves</li> <li>Yes Boom float</li> </ul>	<ul> <li>[X] Yes Joystick controls</li> <li>[] Yes Thumb - Manual</li> <li>[X] Yes Thumb hydraulic</li> <li>[] Yes Counterweight removal sys.</li> <li>[X] Yes Long undercarriage</li> <li>[] Yes Quick coupler manual</li> </ul>	
<ul> <li>[X] Yes Air conditioning</li> <li>[] Yes Stick short</li> <li>[X] Yes Stick medium</li> <li>[] Yes 2 Piece boom</li> <li>[] Yes Long reach arrangement</li> <li>[] Yes Drill arrangement</li> <li>[] Yes Recycling arrangement</li> </ul>	<ul> <li>Yes Cab riser hydraulic</li> <li>Yes Standard car body</li> <li>Yes Hydraulic retractable UC</li> <li>Yes Auxiliary hydraulics</li> <li>Yes Hose rupture valves</li> <li>Yes Boom float</li> <li>Yes Attachment circuits</li> </ul>	<ul> <li>[X] Yes Joystick controls</li> <li>[] Yes Thumb - Manual</li> <li>[X] Yes Thumb hydraulic</li> <li>[] Yes Counterweight removal sys.</li> <li>[X] Yes Long undercarriage</li> <li>[] Yes Quick coupler manual</li> <li>[] Yes Quick coupler hydraulic</li> </ul>	

### **Operators Station**

Seat and armrest	[X] Good
Dash and console	[X] Fair Remarks: Display has small cacks
Floor Board/Mat	[X] Good
Cab glass	[X] Good
Mirrors	[X] Good
Interior light	[X] Good

Switches	[X] Good
Wipers	[X] Good
Gauges	[X] Good
Hydraulic controls	[X] Good
Powertrain controls	[X] Good
AC cooling	[X] Good
CAB Interior	[X] Good
Operators station condition summary	
Comment:	

### **Outside appearance**

Steps	[X] Good
Hand rails	[X] Good
Counterweight /	[X] Good
Bumper	
Grill	[X] Good
Hood	[X] Good
Exhaust stack	[X] Good
Pre-cleaner bowl	[X] Good
Front fenders	[X] Good
Hyd tank	[X] Good
Fuel tank	[X] Good
Car body	[X] Good
Fenders	[X] Good
OEM Welds	[X] Good
Sheet metal	[X] Good
Paint	[X] Good
Outside appearance	
condition summary	
Comment:	

## Safety condition

Safety decals in place	[X]Yes
Operators manual	[ X ] No
Safety handles	[X] Good
Seat belt	[X] Good
Horn	[X] Good
Back up alarm	[X] Good
Brake hold	[X] Good
ROPS Structure	[X] Good
Guarding	[X] Good

CAB	[X] Good
Safety condition summary	
summary	
Comment:	

## **Electrical condition**

Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good
Wiring harness's	[X] Good
Key switch	[X] Good
Switches	[X] Good
Lighting	[X] Good
Engine preheater	[X] Good
Batteries / Connections	; [X] Good
Battery disconnect	[X] Good
switch	
Electrical condition	
summary	
0t	
Comment:	

### **Engine condition**

Oil level OK	[X]Yes
Water in oil	[ X ] No
Compression	[X]Yes
Blow by	[ X ] No
Engine knocking	[ X ] No
CE PLATE	[X]Yes
Oil pressure	[X]Good
Oil leaks	[ X ] No
EPA DECAL	[X]Yes
Turbo charger	[X] Good
Exhaust manifold	[X] Good
Muffler	[X] Good
Fuel injection system	[X] Good
Head gasket	[X] Good
Head	[X] Good
Fan guard	[X] Good
Belts & pulleys	[X] Good
Wiring harness	[X] Good
	[,,,] 0000

Starter	[X] Good
Alternator	[X] Good
Seals & gaskets	[X] Good
Engine mounts	[X] Good
Brackets	[X] Good
AC Compressor	[X] Good
Air filters	[X] Good
Engine condition summary	
Comment:	

# Cooling system

Radiator[X] GoodWater pump[X] GoodOil cooler[X] GoodFan[X] GoodFan drive[X] Good	
Oil cooler[X] GoodFan[X] Good	
Fan [X] Good	
Fan drive [X] Good	
Hoses [X] Good	
Cooling system	
Comment:	]

### Hydraulics condition

Boom cylinders Stick cylinders	[ X] Good [ X] Good	
Bucket cylinders	[X] Good	
Blade cylinders	[ ] Good [ ] Fair [	] Poor Remarks:
Thumb cylinders	[ ] Good [ ] Fair [	] Poor Remarks:
Pumps	[X] Good	
Valves	[X] Good	
Hoses	[X] Good	
Fittings	[X] Good	
Tank	[X] Good	
Swing bearing	[X] Good	
Swing gear	[X] Good	
Swing motor	[X] Good	
Hydraulic swivel	[X] Good	
Travel motors	[X] Good	
Pump drive	[X] Good	
Planetaries left	[X] Good	
Planetaries right	[X] Good	

Controls	[X] Good
Overall condition	[X] Good
Summary	
Comment:	

### Boom & arm condition

Lower stick pins	[X] Good
Upper stick pins	[X] Good
Stick condition	[X] Good
Stick length	3.5m
Boom length	5.7m
Lower boom pins	[X] Good
Upper boom pins	[X] Good
Boom condition	[X] Good
Summary	
Comment:	

#### **Bucket & other attachments**

Bucket type / Size	Strickland 36 inch		
Coupler type	Na		
Bucket serial	28685		
Coupler serial	Na		
Bucket W / Teeth	[X]Yes		
Addtl attachments			
Bolt on smooth	[ X ] No		
Bolt on edge	[ ] Good [ ] Fair [ ] Poor Remarks:		
Bucket mounts	[X] Fair Remarks: Slightly worn still operable		
Bucket teeth / Segments	[X] Good		
Bucket sides	[X] Good		
Bucket floor	[X] Fair Remarks: Dendted		
Bucket bottom	[X] Fair Remarks: Dented		
Coupler	[ ] Good [ ] Fair [ ] Poor Remarks:		
Boom / Frame	[X] Good		

Boom / Bucket pins &	[X] Fair Remarks:	Slightly worn still operable
bushings		
Summary		
Comment:		

### Undercarriage condition

Roller frame right	[X] Good
Roller frame left	[X] Good
Track adjusters	[X] Good
Overall condition	[X] Good
Links left	
Links left	60%
Internal pin wear left	
Internal pin wear left	60%
External pin wear left	
External pin wear left	60%
Trackshoe/ Grouser left	
Trackshoe/ Grouser left	60%
Front Idler left	
Front Idler left	60%
Sprockets left	
Sprockets left	60%
Front Carrier Rollers left	
Front Carrier Rollers left	60%
Center Carrier Rollers left	
Center Carrier Rollers left	60%
Rear Carrier Rollers left	
Rear Carrier Rollers left	60%
Links right	
Links right	60%
Internal pin wear right	
Internal pin wear right	60%
External pin wear right	

External pin wear right	60%
Trackshoe/ Grouser right	
Trackshoe/ Grouser right	60%
Front Idler right	
Front Idler right	60%
Sprockets right	
Sprockets right	60%
Front Carrier Rollers right	
Front Carrier Rollers right	60%
Center Carrier Rollers right	
Center Carrier Rollers right	60%
Rear Carrier Rollers right	
Rear Carrier Rollers right	60%
Bottom rollers S or D	
Undercarriage brand	
Link part number	
Pins & bushings turned	
Comment:	

### Bottom rollers S or D

Bottom rollers S or D left (mm)
mm
Bottom rollers S or D right (%)
Bottom rollers S or D right (mm)
mm
Bottom rollers S or D left (%)
60%
Bottom rollers S or D left (mm)
mm
Bottom rollers S or D right (%)
60%
Bottom rollers S or D right (mm)
mm
Bottom rollers S or D left (%)
60%
Bottom rollers S or D left (mm)
mm
Bottom rollers S or D right (%)
60%
Bottom rollers S or D right (mm)
mm
Bottom rollers S or D left (%)
60%

Bottom rollers S or D left (%)
60%
Bottom rollers S or D left (mm)
mm
Bottom rollers S or D right (%)
60%
Bottom rollers S or D right (mm)
mm
Bottom rollers S or D left (%)
60%
Bottom rollers S or D left (mm)
mm
Bottom rollers S or D right (%)
60%
Bottom rollers S or D right (mm)
° ( ,
mm
Bottom rollers S or D left (%)
60%
Bottom rollers S or D left (mm)
mm
Bottom rollers S or D right (%)
60%
Bottom rollers S or D right (mm)
mm

Bottom rollers S or D right (mm)
mm
Bottom rollers S or D left (%)
60%
Bottom rollers S or D left (mm)
mm
Bottom rollers S or D right (%)
60%
Bottom rollers S or D right (mm)
mm
Bottom rollers S or D left (%)
60%
Bottom rollers S or D left (mm)
mm
Bottom rollers S or D right (%)
60%
Bottom rollers S or D right (mm)
mm
Bottom rollers S or D left (%)
60%
Bottom rollers S or D left (mm)
mm
Bottom rollers S or D right (%)
60%

Bottom rollers S Bottom rollers S	mm	Bottom rollers S or D left (%) 60%	Bottom rollers S or I	D right (mm) ] mm
60% Comment:				
General Comments	-			
Legend (5 star rating) Paint general	[ ]5 [ ]4 [ ]3 [ ]2 [ ]Good [ ]Fair [ ]F			

Comment: