

**Lessee: Key Equipment**  
**Contract: 502-7609905-069**

**Unit: 2018 Volvo L90H**

**UNIT # 624169**  
**Location: ASC Construction**  
**Equipment, Buford GA**



### **SPECIFICATIONS**

VIN	624169
LeaseInspector ID #	624169
Year	2018
Model	Volvo L90H
Location City	Buford
Location State	GA
<b>General Specifications</b>	
New Hours	3248
Old Hours	3248

**Lessee: Key Equipment**  
**Contract: 502-7609905-069**

**Unit: 2018 Volvo L90H**

**UNIT # 624169**  
**Location: ASC Construction**  
**Equipment, Buford GA**

**ADDITIONAL FEATURES OF THIS VEHICLE**  
**COMMENTS**

**Appraiser Comments:**

**Creditor Comments:**

**Public Comments:**

**Starts/Runs:** Yes

**Overall:** Fair

**Lessee: Key Equipment**  
**Contract: 502-7609905-069**

**Unit: 2018 Volvo L90H**

**UNIT # 624169**  
**Location: ASC Construction**  
**Equipment, Buford GA**


### DEFICIENCY REVIEW

<b>ITEM</b>	<b>QTY PRICE</b>
1. SCR System Failure Warning - Repaired	\$0.00
2. Full Derate Warning - Repaired	\$0.00
3. Unit Would Turn Over But Not Fire - Repaired	\$0.00
4. Jump Started- Not Repaired - Repaired	\$0.00
5. Left Mirror Broken - Replaced	\$0.00
6. Right Lower Step Bent- Repaired	\$0.00
7. Right Front Tires Cut- Not Repaired	\$0.00
8. Dealer to Determine if Serive is Due- Not Due	\$0.00
9. Dealer to Verify Tire Cuts are Cosmetic Only- Verified	\$0.00
<b>Total</b>	<b>\$0.00</b>

Lessee: Key Equipment  
Contract: 502-7609905-069

Unit: 2018 Volvo L90H

UNIT # 624169  
Location: ASC Construction  
Equipment, Buford GA



**Lessee: Key Equipment**  
**Contract: 502-7609905-069**

**Unit: 2018 Volvo L90H**



**UNIT # 624169**  
**Location: ASC Construction**  
**Equipment, Buford GA**



Lessee: Key Equipment  
Contract: 502-7609905-069

Unit: 2018 Volvo L90H

UNIT # 624169  
Location: ASC Construction  
Equipment, Buford GA



Lessee: Key Equipment  
Contract: 502-7609905-069

Unit: 2018 Volvo L90H

UNIT # 624169  
Location: ASC Construction  
Equipment, Buford GA