

Lessee: Argos USA
Contract: 502-7694383-045

Unit: 2018 Volvo L90H

UNIT # 624235
Location: ASC Construction
Equipment, Buford GA



VIN	624235
LeaseInspector ID #	624235
Year	2018
Model	Volvo L90H
Location City	Buford
Location State	GA
General Specifications	
New Hours	2566
Old Hours	2564

Lessee: Argos USA
Contract: 502-7694383-045

Unit: 2018 Volvo L90H

UNIT # 624235
Location: ASC Construction
Equipment, Buford GA

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

Lessee: Argos USA
Contract: 502-7694383-045

Unit: 2018 Volvo L90H

UNIT # 624235
Location: ASC Construction
Equipment, Buford GA

ITEM	QTY PRICE
1. Right Side Fender Step Damaged- Repaired	\$0.00
2. Clean Machine- Repaired	\$0.00
3. 2 Front Tires Past 50%- Not Repaired	\$0.00
4. Dealer to Determine if Service is Due- Not Due	\$0.00
5. Dealer to Verify Tire Cuts are Cosmetic Only- Cosmetic	\$0.00
6. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00
7. Oil Seep on Right Side of Engine- Repaired	\$0.00
8. Air Cleaner Dirty- Repaired	\$0.00
9. Left Mirror Damaged, Missing- Repaired	\$0.00
10. Front Heater Controls Damaged- Repaired	\$0.00
11. Radiator Grille Damaged- Repaired	\$0.00
12. Right Front Fender Torn- Repaired	\$0.00
13. Left Front Fender Torn- Repaired	\$0.00
14. Right Rear Fender Torn/Damaged- Repaired	\$0.00
15. Left Rear Fender Torn- Repaired	\$0.00
Total	\$0.00

Lessee: Argos USA
Contract: 502-7694383-045

Unit: 2018 Volvo L90H


UNIT # 624235
Location: ASC Construction
Equipment, Buford GA



Lessee: Argos USA
Contract: 502-7694383-045

Unit: 2018 Volvo L90H

UNIT # 624235
Location: ASC Construction
Equipment, Buford GA



Lessee: Argos USA
Contract: 502-7694383-045

Unit: 2018 Volvo L90H

UNIT # 624235
Location: ASC Construction
Equipment, Buford GA



Lessee: Argos USA
Contract: 502-7694383-045

Unit: 2018 Volvo L90H

UNIT # 624235
Location: ASC Construction
Equipment, Buford GA

