## **VOLVO - INSPECTION REPORT**

# Volvo, A40g - Articulated haul trucks

#### **Images**















Cor		

Country: US Date: 06/17/2019 Make: Volvo Serial number: 341243

Trans S/N: 1700106721

Dealer: Arnold Machinery Company Inspector: Justin Mcdonald

Model: A40g Engine S/N: 094066 Location: Las Vegas Year: 2016 Hours: 4415 Matris hours:

Comment:

### **Equipped Configuration**

[X]Yes Standard Cab
[]Yes Water Tank
[]Yes LED Light
[X]Yes Strobe Light
[]Yes Hydraulic switch control
[X]Yes Hydraulic lever control
[]Yes Auto Lube System
[]Yes Fire Suppression System
[X]Yes Mud Flaps

Yes Scraper ARRG.
Yes Low Profile Cab
Yes Standard Body
Yes Extra Spill Guard
Yes Exhaust Body Heat
Yes Overhung Tailgate
Yes Underhung Tailgate
Yes Underground ARRG.

[ ] Yes Fuel Heater
[ ] Yes Full Suspension
[ ] Yes Frame Ext.
[ ] Yes Onboard Weight Sys.
[ X ] Yes Bed Liner Metal
[ ] Yes Bed Liner Plastic
[ X ] Yes Back Up Camera
[ ] Yes Fast Fuel

### **Operators Station**

Comment:

Seats and armrest [X] Good

Dash and console [X] Good

Floor Board/Mat [X] Good

Cab glass [X] Good

Mirrors [X] Good

Interior light [X] Good

Switches [X] Good

Wipers [X] Good

Gauges [X] Good

Hydraulic controls	[X] Good
Powertrain controls	[X] Good
AC cooling	[X] Good
CAB Interior	[X] Good
Operators station condition summary	
Comment:	
Outside appearance	ce
Steps	[X] Good
Hand rails	[X] Good
Counterweight /	[X] Good
Bumper	
Grill	[X] Good
Hood	[X] Good
Exhaust stack	[X] Good
Pre-cleaner bowl	[X] Good
Front fenders	[X] Good
Hyd tank	[X] Good
Fuel tank	[X] Good
Def tank	[X] Good
Front frame & welds	[X] Good
Rear frame & welds	[X] Good
Sheet metal	[X] Good
Paint	[X] Good
Outside appearance condition summary	
Comment:	
Safety condition	
Safety decals in place	[X]Yes
Operators manual	[X]Yes
Safety handles	[X] Good
Seat belt	[X] Good
Horn	[X] Good
Back up alarm	[X] Good
Brake lights	[X] Good
Turn signals	[X] Good

Hazard lights

[X] Good

ROPS Structure	[X] Good
CAB	[X] Good
Safety condition summary	
Comment:	
Electrical condition	1
Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good
Wiring harness's	[X] Good
Key switch	[X] Good
Switches Lighting	[X] Good
Engine preheater	[X] Good
Batteries / Connections	
Battery disconnect	[X] Good
switch	
Electrical condition summary	
Comment:	
Engine condition	
Oil level OK	[X]Yes
Water in oil	[X] No
Compression in radiator	[X] No
Blow by	[X] No
Engine knocking	[X] No
CE PLATE	[X]Yes
Oil pressure	[X] Good
Oil leaks	[X] No
EPA DECAL	[X]Yes
Turbo charger	[X] Good
Exhaust manifold	[X] Good
Muffler	[X] Good
Fuel injection system	
	[X] Good

[X] Good

Head

Fan guard	[X] Good
Belts & pulleys	[X] Good
Wiring harness	[X] Good
Starter	[X] Good
Alternator	[X] Good
Seals & gaskets	[X] Good
Engine mounts	[X] Good
Brackets	[X] Good
AC Compressor	[X] Good
Air filters	[X] Good
Engine condition summary	45 psi idle
Comment:	
Coolin v oveteve	
Cooling system	
Coolant color	Yellow
Radiator	[X] Good
Water pump	[X] Good
Oil cooler	[X] Good
Fan	[X] Good
Fan drive	[X] Good
Hoses	[X] Fair Remarks:
Cooling system summary	
,	
Comment:	
Transmission co	ondition
Oil level OK	[X]Yes
Water in oil	[X] No
Any leaks	[X] No
Torque converter	[X] Good
Case	[X] Good
Pump	[X] Good

Hoses	[X] Good
Retarder	[X] Good
Transfer case	[X] Good
Shifting forward	[X] Good
Shifting reverse	[X] Good
Transmission summary	175 psi idle
Comment:	
Axels-Final Drives-Brakes	

Front differential [X]Good Center differential [X]Good Rear differential [X]Good Differential supports [X]Good Drive shafts [X]Good **UV** Joints [X]Good Planetaires front [X] Good Planetaires center [X]Good Planetaires rear [X]Good Hoses / Lines [X]Good Torsion rods [X]Good Holds in park [X]Yes Brakes wet [X]Yes Holds thru all gears [X]Yes Brakes dry [X]Yes Brake disk / calipers [X]Good Brake lines [X]Good Seals [X]Good Parking brake [X]Good Summary Comment:

## Steering & articulation condition

Steering cylinders [X] Good Pumps [X] Good Valves [X] Good

Lines / Hoses	[X] Good
Secondary steering	[X] Good
Steering pins & bushings	[X] Fair Remarks: Slightly worn still operable
Steering wheel tilt &	[X] Good
function	
Articulation pins &	[X] Fair Remarks: Slightly worn still operable
bushings	[X] Fall Perialis.
Summary	
,	
Comment:	
Hydraulics conditi	on
riyaradiles coriditi	UII
Bed lift cylinders	[X] Good
Pumps	[X] Good
Valves	[X] Good
Hoses	[X] Good
Fittings	[X] Good
Tank	[X] Good
Controls	[X] Good
Bed float	[X] Good
Operational condition	[X] Good
Summary	
Comment:	
Bed & other attack  Bed type / Size	hments
Tailgate S / N	
Bed serial	
Addtl attachments	
7 add dilaoimonto	
Spill guard	[X] Good
Body	[X] Good
Bed liner	[X] Good
Bed sides	[X] Good
Bed floor	[X] Good
Wear plates	[X] Good
Tailgate	[X] Good
Pins & bushings	[X] Fair Remarks: Slightly worn still operable
Summary	
•	
Comment:	
Tires & rims	
Make	Michelin L1
mano	IVIICITEIII LI
Serial	UPE 0828V7A 44/32
% Remaining	
% Kemaminu	

Make	Michelin L2
Serial	UPE 0825V0A 45/32
% Remaining	
Make	Michelin L3
Serial	UPE 0817V8A 43/32
% Remaining	
Make	Michelin R1
Serial	UPE 0810V5A 44/32
% Remaining	
Make	Michelin R2
Serial	UPE 0829V6A 46/32
% Remaining	
Make	Michelin R3
Serial	UPE 0813V2A 42/32
% Remaining	
Recapped	[X] No
Tread cuts	[X] Yes Remarks: Minimal
Side wall cuts	[X] Yes Remarks: L1 minimal outside L2 minimal outside
Tire size the same	[X] Yes Remarks: 29.5 R 25
Overall tire condition	[X] Good
Rims	[X] Good
Lug nuts & studs	[X] Good
Comment:	
General Comment	s
Legend (5 star rating) Paint general	[ ]5 [ ]4 [ ]3 [ ]2 [ ]1 [ ]Good [ ]Fair [ ]Poor Remarks:
Comment:	