2018 Volvo A45G

Aring Equipment Co DeForest, WI 608-846-9600

- Rear vision system
- Air ride seat
- Air conditioning
- Rotating beacon
- Body exhaust heating kit

• SMU/Hours: 2354

• Overall: Fair

- Radio
- Differential locks

Serial #: 342416

- Computer display
- Mudflaps

Tailgate

Start Run: Yes

Insp Date: 4/1/2020









General Appearance

Radiator 0	Grille:	Good	Precleaner b	owl:	Good
Radiator Shroud: Good		Fuel Tank:		Good	
Engine Enclosure: Good		Good	Cab Doors:		Good
Hood:		Good	Bumper:		Fair
Stack:		Good	Cab:		Good
Right fron	t fender:	Good	Steps:		Fair
Left front fender:		Good	Grab Irons/Handrails:		Good
Rear frame:		Good	Paint:		Good
Front frame: Good		Oil Sample Taken:		No	
LEGEND C	F CONDITION	IS:			
Excellent -	New condition	on. No Repairs Necessary.	Poor -	Obvious we necessary.	ear and/or damage. Repairs
Good -		t wear or damage, perates correctly. No Repairs	Not Applicable	- Does not a	pply to this unit
Fair - Wear and/or damage apparent. Functions, but not correctly. Repairs recommended.					

Interior Section

Glass:	Good	Neutral Start Switch:	Good
Mirrors:	Good	Fire Suppression System:	Not Available
Seat Belt:	Good	Horn:	Good
Back Up Alarm:	Good		
Fan Guards:	Good		
NOTES:		•	
Dook Consoler	Orad	L Out Out binne	Ozzal
Dash Console:	Good	Seat Cushion:	Good
Meter:	Good	Arm Rests:	Good
Gauges:	Good	Floor Boards/Mats:	Good
Control Pattern Decals:	Good	EMS Panel:	Good
Control Pattern Decais.	Good	Warnings:	Good
Switches:	Good		
	Good	Door Latches:	Good
Switches:		Door Latches: Current Parts Manual:	Good No
Switches: Windshield Wipers:	Good		

Power Systems

Engine Make Model:	Volvo D16J	Oil Pressure:	Normal	
Engine S/N:	112079	Smoke:	No	
Engine Hours:	2354	Smoke Color:	Light	
Oil Leaks:	No	TurboCharger:	Good	
Blow-by:	No	Fuel Injection System: Good		
Knocking:	No	Governor:	Good	
Compression in Radiator:	No	Engine Supports:	Good	
Water in Oil:	No	Air Cleaners:	Fair	
Fluid Level OK?:	Yes			
Anit-Freeze Color:	Gold			
Radiator:	Good	Fan:	Good	
Coolers:	Good	Fan Drive:	Good	
Coolers: Hoses:	Good Good	Fan Drive: Belts:	Good Good	
Coolers: Hoses: Water Pump: NOTES:	Good Good	Fan Drive: Belts:	Good Good	
Coolers: Hoses: Water Pump: NOTES: Batteries:	Good Good Good	Fan Drive: Belts: Pulleys:	Good Good Good	
Coolers: Hoses: Water Pump:	Good Good Good	Fan Drive: Belts: Pulleys: Wiring:	Good Good Good	

Power Systems - Continued

Transmission Serial #:	1700109632	Seals:	Good	
Transmission Type:	Auto	Torque Converter:	Good	
Transmission Speeds:	9 F 3 Rev	Temp/Pressure Gauges:	Good	
Transmission Forward:	Good	Transmission Fluid:	Good	
Transmission Reverse:	Good	Is the Transmission Noisy?:	No	
Case:	Good	Transmission Retarder:	No	
Controls:	Good			
NOTES:				
Steering Linkage:	Good	Left steering cylinder:	Good	
Steering Valve:	Good	Right steering cylinder:	Good	
Steering Pump:	Good	Steering joints:	Good	
Articulation P & B:	Good			
NOTES:				
Mechanism:	Wet	Lines:	Good	
Туре:	Pedal	Compressor:	Not Available	
Perfomance:	Good	Brake linkage:	Good	
Brake drums:	Not Available	Master cylinder:	Good	
Rotors:	Not Available	Parking brake:	Good	
Control Valve:	Good			
NOTES:				
Front axle:	Good	Rear axle housing:	Good	
Front differential:	Good	U-Joints:	Good	
Rear axles:	Good	Front suspension:	Good	
Rear differentials:	Good	Rear suspension:	Good	
Front wheel lugs & rims:	Good	Front a-stay:	Good	
Rear wheel lugs & rims:	Good	Rear a-stay:	Good	
Front axle bolts:	Good			
Rear axle bolts:	Good			
Front axle housing:	Good			
NOTES:				

2018 Volvo A45G (Continued)

Serial #: 342416

Hydraulics

Right dump cylinder:	Good	Valves:	Good	
•				
Left dump cylinder:	Good	Control linkage:	Good	
Hose lines:	Good	Reservoir:	Good	
Pumps:	Good	Dump cycle test:	Good	
NOTES:		*		

Dump Body

Body type:	General Purpose	Body pins and bushings:	Good
Body bottom:	Good	Body liner:	Good
Body sides:	Fair	Tail gate adapter:	Good
Rubber pads:	Good	Tail gate:	Good
Body mounts:	Good	Front spill guard:	Good

Tires

Front Tire Size:	Left: 29.5R25 85%	- Right: 29.5R25 - 87%	Rear	Tire	Size 1:	Left: 29.5R25 89%	- Right: 29.5R25 - 85%
Front Tire Brand: Left:	Bridgestone Ri	ght: Bridgestone	Rear	Tire	Brand 1: Le	ft: Bridgestone Ri	ght: Bridgestone
Front Tire Radial or Bias:	Left: Radial	Right: Radial	Rear	Tire	Radial or Bias:	Left: Radial	Right: Radial
Front Tire Measurement:	Left: 47/32	Right: 48/32	Rear	Tire	Measurement 1:	Left: 49/32	Right: 47/32
			Rear	Tire	Size 2:	Left: 29.5R25 87%	- Right: 29.5R25 - 87%
			Rear	Tire	Brand 2: Le	ft: Bridgestone Ri	ght: Bridgestone
			Rear	Tire	Radial or Bias:	Left: Radial	Right: Radial
			Rear	Tire	Measurement 2:	Left: 48/32	Right: 48/32
NOTES:			•				
Tread Depth Wear Based Or	n 55/32nds New	1					

Comments

Public Comments:		

Reconditioning

	ITEM	QTY PRICE
1.	+ Rear Work Light Inop	\$0.00
2.	+ Body Side Scraped	\$0.00
3.	+ All Tires Cut/Gouged	\$0.00
4.	+ Deidentify	\$0.00
5.	+ Bumper Scraped	\$0.00
6.	+ Left Side Bottom Step Bent	\$0.00
7.	+ Right Side Bottom Step Bent	\$0.00
8.	+ Clean Machine	\$0.00
To	otal	\$0.00





























