

Lessee: Key Equipment
Contract: 502-7609905-071

Unit: 2018 Volvo EC220EL

UNIT # 310579
Location: ASC Construction
Equipment, Buford GA



SPECIFICATIONS

VIN	310579
LeaseInspector ID #	310579
Year	2018
Model	Volvo EC220EL
Location City	Buford
Location State	GA
General Specifications	
New Hours	2449
Old Hours	2440

Lessee: Key Equipment
Contract: 502-7609905-071

Unit: 2018 Volvo EC220EL

UNIT # 310579
Location: ASC Construction
Equipment, Buford GA

ADDITIONAL FEATURES OF THIS VEHICLE
COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

Lessee: Key Equipment
Contract: 502-7609905-071

Unit: 2018 Volvo EC220EL

UNIT # 310579
Location: ASC Construction
Equipment, Buford GA

DEFICIENCY REVIEW


ITEM**QTY PRICE**

1. Dealer to Determine if Service is Due- Not Due	\$0.00
2. Right Body Step Bent- Repaired	\$0.00
3. Rear Camera Out of Alignment- Repaired	\$0.00
4. Left Front Cab Light Missing- Replaced	\$0.00
5. Right Mirror Damaged- Replaced	\$0.00
6. Radiator Grille Damaged- Not Replaced	\$0.00
7. Front Bottom Rail Bent- Not Repaired	\$0.00
8. Left Side Lower Rail Bent- Not Repaired	\$0.00
Total	\$0.00

Lessee: Key Equipment
Contract: 502-7609905-071

Unit: 2018 Volvo EC220EL

UNIT # 310579
Location: ASC Construction
Equipment, Buford GA



Lessee: Key Equipment
Contract: 502-7609905-071

Unit: 2018 Volvo EC220EL

UNIT # 310579
Location: ASC Construction
Equipment, Buford GA

