

2018 Volvo EC50EL

Serial #: 0514

<p>Rudd Equipment Nitro, WV 304-755-7788</p>	<ul style="list-style-type: none">• Auxillary hydraulic lines• Hand control pattern changer• Seat w/suspension, headrest and joystick adjustment• SMU/Hours: 582• Overall: Fair• Start Run: Yes• Insp Date: 5/19/2020
--	---



NO
PICTURE
AVAILABLE



2018 Volvo EC50EL

(Continued)

Serial #: 0514

General Appearance

GENERAL:			
Radiator Grille:	Good	Main Frame Welds:	Good
Radiator Shroud:	Good	Car Body:	Good
Engine Enclosure:	Good	Bumper:	Good
Hood:	Good	Counterweight:	Good
Stack:	Good	Cab:	Good
Catwalk:	Good	Cab Door:	Good
Fuel Tank:	Good	Steps or Ladder:	Good
Crankcase Guard:	Good	Grab Irons/Handrails:	Good
Precleaner bowl:	Good	Paint:	Good
Battery Box:	Good	Oil Sample Taken:	No
NOTES: .			

2018 Volvo EC50EL

(Continued)

Serial #: 0514

Interior Section

SAFETY ITEMS:			
Glass:	Good	Neutral Start Switch:	Good
Mirrors:	Good	Fire Suppression System:	Not Available
Seat Belt:	Good	Horn:	Good
Back Up Alarm:	Good	ROPS:	Yes
Fan Guards:	Good	FOPS:	No
NOTES:			
OPERATOR AREA:			
Dash Console:	Good	Seat Cushion:	Good
Meter:	Good	Arm Rests:	Good
Gauges:	Good	Floor Boards/Mats:	Good
Control Pattern Decals:	Good	EMS Panel:	Good
Switches:	Good	Warnings:	Good
Windshield Wipers:	Good	Door Latches:	Good
Heater:	Good	Current Parts Manual:	No
A/C:	Good	Current Safety Manual:	Yes
Interior Lights:	Good	Current O&M Manual:	Yes
NOTES:			

2018 Volvo EC50EL

(Continued)

Serial #: 0514

Power Systems

ENGINE:			
Engine Make Model:	Volvo D13J	Oil Pressure:	Normal
Engine S/N:	729382A	Smoke:	No
Engine Hours:	582	Smoke Color:	Not Applicable
Oil Leaks:	No	TurboCharger:	Good
Blow-by:	No	Fuel Injection System:	Good
Knocking:	No	Governor:	Good
Compression in Radiator:	No	Engine Supports:	Good
Water in Oil:	No	Air Cleaners:	Good
Fluid Level OK?:	Yes	+ Last Scheduled Oil Sample:	-
Anit-Freeze Color:	Yellow	-	-
		+ Last Preventive Maintenance:	-
		-	-
NOTES:			
COOLING SYSTEM:			
Radiator:	Good	Fan:	Good
Coolers:	Good	Fan Drive:	Good
Hoses:	Good	Belts:	Good
Water Pump:	Good	Pulleys:	Good
NOTES:			
ELECTRICAL SYSTEM:			
Batteries:	Good	Wiring:	Good
Battery Cables:	Good	Pre-Heater:	Good
Starter:	Good	Lighting:	Good
Alternator:	Good		
NOTES:			

2018 Volvo EC50EL

(Continued)

Serial #: 0514

Power Systems - Continued

TRANSMISSION:			
Type:	Hydrostatic	Controls:	Good
Speeds:	Fair	Seals:	Good
Transmission Forward:	Good	Temp/Pressure Gauges:	Good
Transmission Reverse:	Good	Is the Transmission Noisy?:	No
Case:	Good		
NOTES:			
FINAL DRIVE:			
Planataries:	Good	Housings:	Good
NOTES:			

2018 Volvo EC50EL

(Continued)

Serial #: 0514

Hydraulics

HYDRAULICS:			
Tank:	Good	Pumps:	Good
Hydraulic Lines:	Good	Swing Gear:	Good
Boom Cylinders:	Good	Pump Drive:	Good
Stick Cylinder:	Good	Valves:	Good
Bucket Cylinder:	Good		
NOTES:			

Boom/stick/bucket

BOOM/STICK/BUCKET:			
Boom type:	Single with 2 Hydraulic Cylinders	Bucket type:	Digging
Boom length:	20' 4"	Bucket width:	56"
Boom condition:	Good	Bucket edge:	Good
Boom pins:	Good	Bucket sides:	Good
Boom/arm side clearance:	Good	Bucket bottom:	Good
Boom/arm alignment:	Good	Bucket linkage:	Good
Arm length:	12' 10"	Bucket pins:	Good
Arm condition:	Good	Quick attach:	Not Available
Arm pins:	Good	Teeth:	Good
Bucket make:	Werk Brau	Cutting edge:	Not Available
NOTES:			

2018 Volvo EC50EL

(Continued)

Serial #: 0514

Attachments

ATTACHMENTS:			
Grapple:	No	Stump grinder:	No
Compactor:	No	Slurry stirrer:	No
Rotary cutter:	No	Ripper:	No
Hammer:	No	Brush rake:	No
Brush cutter:	No	Blade:	No
NOTES:			

2018 Volvo EC50EL

(Continued)

Serial #: 0514

Undercarriage

UNDERCARRIAGE:								
TRACK RAILS:				TRACK PADS:				
Brand:	Volvo			Pad Width:	800mm			
Pitch:	-			Pad Type:	Triple			
# Links:	Left: 48	Right: 48		Grouser:	Left: 35mm - 7%	Right: 35mm - 7%		
Type:	NA			Left Scalloped:	NO			
Rail:	Left: 124mm - 10% Right: 125mm - 0%			Right Scalloped:	NO			
Stretch:	-							
TRACK PINS/BUSHINGS:				IDLER:				
Average Diameter:	Left: 70mm - 27% Right: 70mm - 27%			Idler Measurement:	Left	Right		
Turned:	NO			Front Idler	22mm - 0%	22mm-0%		
				Rear Idler	-	-		
ROLLERS - CARRIERS:				SPROCKET:				
# Of Rollers	1	2		Measure of 3 Teeth	Left	Right		
Left:	162mm - 16%	163mm - 11%			Good	Good		
Right:	163mm - 11%	163mm - 11%						
ROLLERS - BOTTOM:								
# Of Rollers:	1	2	3	4	5	6	7	8
Left	190mm - 0%	190mm - 0%	-	190mm - 0%	190mm - 0%	-	190mm - 0%	190mm - 0%
Right	190mm - 0%	190mm - 0%	-	190mm - 0%	190mm - 0%	-	190mm - 0%	190mm - 0%
CONDITION:					MAINTENANCE:			
Track Frame:	Left	Right	Good		+Last Track Inspection:			
					-			
NOTES:								

2018 Volvo EC50EL

(Continued)

Serial #: 0514

Comments

COMMENTS:
Creditor Comments:
Public Comments:

2018 Volvo EC50EL

(Continued)

Serial #: 0514

Reconditioning

DEFICIENCY REVIEW:		
ITEM	QTY	PRICE
2. dealer to determine if service is due		\$0.00
Total		\$0.00

2018 Volvo EC50EL

(Continued)




Serial #: 0514



2018 Volvo EC50EL

(Continued)


Serial #: 0514



2018 Volvo EC50EL

(Continued)


Serial #: 0514



2018 Volvo EC50EL

(Continued)

Serial #: 0514



2018 Volvo EC50EL

(Continued)


Serial #: 0514



2018 Volvo EC50EL

(Continued)


Serial #: 0514



2018 Volvo EC50EL

(Continued)




Serial #: 0514



2018 Volvo EC50EL

(Continued)

Serial #: 0514



2018 Volvo EC50EL

(Continued)

Serial #: 0514



2018 Volvo EC50EL

(Continued)

Serial #: 0514



2018 Volvo EC50EL

(Continued)

Serial #: 0514



2018 Volvo EC50EL

(Continued)

Serial #: 0514

