Lessee: Key Equipment
Contract: 502-7609905-066

Unit: 2018 Volvo L90H

UNIT # 624171
Location: ASC Construction Equipment, Buford GA

SPECIFICATIONS

VIN	624171
LeaseInspector ID #	624171
Year	2018
Model	Volvo L90H
Location City	Buford
Location State	GA
General Specifications	
New Hours	3079
Old Hours	3078

Lessee: Key Equipment
Contract: 502-7609905-066

Unit: 2018 Volvo L90H

UNIT # 624171
Location: ASC Construction Equipment, Buford GA

ADDITIONAL FEATURES OF THIS VEHICLE

COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes
Overall: Fair

Lessee: Key Equipment
Contract: 502-7609905-066

Unit: 2018 Volvo L90H

UNIT # 624171
Location: ASC Construction Equipment, Buford GA

DEFICIENCY REVIEW

ITEM	QTY	PRICE
1. Deidentify- Not Repaired		$0.00
2. Both Front Fendesr/Brackets Missing- Not Replaced		$0.00
3. Both Rear Tires Past 50%- Not Replaced		$0.00
4. Dealer to Determine is Servive is Due- Done		$0.00
5. Dealer to Verify Tire Cuts are Cosmetic Only- Verified		$0.00
6. 1 Dash Blank Missing- Replaced		$0.00
7. Right Rear Fender Missing Flare- Not Replaced		$0.00
8. Left Rear Fender Missing Flare- Not Replaced		$0.00
9. 1 Left Cab Light Inop- Repaired		$0.00
10. Seep Under Cab- Repaired		$0.00
11. Right Windshield Cracked- Replaced		$0.00
Total		**$0.00**

Lessee: Key Equipment
Contract: 502-7609905-066

Unit: 2018 Volvo L90H

UNIT # 624171
Location: ASC Construction Equipment, Buford GA







Lessee: Key Equipment
Contract: 502-7609905-066

Unit: 2018 Volvo L90H

UNIT # 624171
Location: ASC Construction Equipment, Buford GA



Lessee: Key Equipment
Contract: 502-7609905-066

Unit: 2018 Volvo L90H

UNIT # 624171
Location: ASC Construction Equipment, Buford GA